Copy bat b

19 December 1961

SUBJECT:

The Record

25X1A

Freject Meeting - 15 December 1901

REFERENCE:

(a) OEC-2751 deted 4 Dec. 61 - Subject as above.

1. Delivery Schafules

(a) Currently anticipated deliveries of initial production hardware are running approximately one month behind schedule. On 15 December the following picture was presented:

Ungit No.	Proposed Application	Committed Delivery	Dalivery Anticipated 1 December	Delivery Amticipated 15 December
				America African Commission of the Commission of
Main Con	trol		4	and the state of the state of
1	Eac. Derc.	11/30/61	12/15/61	12/26/61
2	Ros. Deep.	12/31/61	12/31/61	12/31/61
2 3	1/2 711abt	12/31/61	1/15/62	1/29/62
Z	No Flight	12/31/61	1/16/62	1/31/62
\$	He Flicht	1/31/62	Not Listed	2/10/62
4 5 6	nz Plight	1/31/62	Not Listed	5/36/62
7	TO FLIGHT	1/31/62	Not Unted	2/17/62
Afterbur	wer -			
Control		e America Palan	n a de a del a	an fan lês
1	Dag. Davy.	11/30/61	12/11/61	12/19/61
	My Flight	12/31/61	1/5/62	1/10/62
2 3 4 5 6	No Flight	12/31/61	1/11/62	1/22/62
L	No Flight	1/31/62	Not Listed	1/28/62
Š	12 Might	1/31/62	Not Listed	2/8/62
6	No Flight	1/31/62	Bot Listed	2/15/62
Exhaust	Mozele			
Control		i		a la lkin
1	No Plight	12/31/61	12/31/61	1/8/62
2	no Plight	12/31/61	12/31/61	1/8/62

DOCUMENT NO. 29
NO CHANGE IN CLASS. V
L1 DECLASSIFIED
CLASS. CHANGED TO: TS S C 76/1/2
NEXT REVIEW DATE:

25X1

OXC-2E24 Page 2

- (b) As reported in reference (a) memorandum, contributing factors to manufacturing delays stem from casting quality, inspection requirements and procedural delays, and engineering change volume.
- (c) In order to minimise delay, the following setions are underway:
 - (1) Accelerate deliveries of new castings when and whenever possible
 - (2) Investigate improvement of welding techniques and materials in order to reduce current centing rework time.
 - (3) Periodically review imspection procedures in order to sesure proper sequence and expeditions handling of material.

(4)	(Project Factory Manager) has been
replaced by	es Project Production Manager.
	previously Project Production Menager)
will pow reper	to Chemres such as this
will be made as	necessary in order to strengthen project
organisation.	

- (5) Only those engineering changes considered mandatory for operational reliability are being incorporated. All changes must be so configured as to minimise change in edjacent equipment.
- (6) Periodically review manufacturing methods is order to reduce assembly cycle time as soon as possible.
- (7) Three shift engineering lisison coverage is underway in order to assist assembly and test operations.
- (8) Three shift seven day per week schedules are in effect in all areas of machining, essembly, and test for those components behind echedule.

2. Clorida Impertory:

The following represents an inventory of experimental controls currently in homes at FAM Florida:

25X1A 25X1A 25X1A 25X1A

Approved For Release 2002/10/30 : CIA-RDP81B00879R001000070116-0

Page 3

	Ameter of Unite	Macher of units
	English Pandy	on Bench Tent
No. of the contract of the con		
Main Control	•	3
Afterburner Control	.	0
Execut Percle	2	0
Control		

SIGNED

25X1A

Distributions

25X1A